

**Table 6**  
**Findings of Suitability to Transfer**  
**SUPERFOST No. 3 Transfer**  
**Summary of Asbestos Containing Materials Building Survey**  
**Fort McClellan, Alabama**  
Page 1 of 1

Building Number	Year Built	Description	Description & Location of ACM	Condition
269	1918	Transient Quarters	Friable, hand-formed, asbestos containing insulation compound is applied to the fittings of pipes located in the crawlspace of the building.	Good
			Friable cementitious asbestos containing material is found on straight runs of pipes located in the crawlspace of the building.	Fair
			Non-friable 9x9-inch asbestos containing vinyl floor tile is found in the basement of the building. Black, asbestos containing mastics are present below vinyl floor tiles in the building.	Poor
3185	1954	Limited Use Instruction	Friable brown paper insulation and the elbow putty located on pipes.	Good
3189	1954	Limited Use Instruction	Non-friable presumed asbestos containing 12x12-inch floor tile and mastic.	Good